

Huawei Access Switch Node Alarm SOP - Node ID: Huawei-Access-Chennai-TN-100

Node: Huawei-Access-Chennai-TN-100 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_9106

Description

This SOP describes the steps to diagnose and resolve the ALARM_9106 critical alarm on the Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-100.

Potential Root Causes

Cause	Probability
Hardware Fault	High
Software Bug	Medium
Misconfigured Interface	Low

Diagnostic Commands

```
display this
display version
display hardware
display interface GigabitEthernet 0/0/1
```

Resolution Steps

Step 1: {'Step': 'Restart the Interface', 'Description': 'Use the command "undo interface GigabitEthernet 0/0/1" followed by "interface GigabitEthernet 0/0/1" to restart the interface.', 'CLI_Command': 'undo interface GigabitEthernet 0/0/1\r\ninterface GigabitEthernet 0/0/1'}

Step 2: {'Step': 'Check and Configure the Interface', 'Description': 'Verify the interface configuration and make necessary changes using the command "interface GigabitEthernet 0/0/1".', 'CLI_Command': 'interface GigabitEthernet 0/0/1'}

Step 3: {'Step': 'Upgrade the Software', 'Description': 'Check for software updates and upgrade the switch software to the latest version.', 'CLI_Command': 'upgrade package'}

Post-Check Verification

```
display alarm
display interface GigabitEthernet 0/0/1
display version
```