

Huawei Access Switch Node Alarm Resolution SOP

Node: Huawei-Access-Chennai-TN-84 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_2228

Description

This SOP outlines the steps to resolve the ALARM_2228 Major Alarm on Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-84.

Potential Root Causes

Cause	Probability
Optical Fiber Cut or Damage	High
Transceiver Module Failure	Medium
Switch Hardware Failure	Low

Diagnostic Commands

```
display transceiver info
display optical-fiber-info
display hardware-diagnostic result
```

Resolution Steps

- Step 1: {'Step': '1. Check the optical fibers and transceiver modules for any signs of damage.', 'Action': 'Verify the condition of the optical fibers and transceiver modules.'}
- Step 2: {'Step': '2. Replace the transceiver module if it is faulty.', 'Action': 'Replace the transceiver module with a new one using the command: replace transceiver '}
- Step 3: {'Step': '3. Check the switch hardware for any faults.', 'Action': 'Run the command: display hardware-diagnostic result to check for any hardware faults.'}
- Step 4: {'Step': '4. Replace the switch if it is faulty.', 'Action': 'Replace the switch with a new one using the command: replace system '}

Post-Check Verification

```
display transceiver info
display optical-fiber-info
display hardware-diagnostic result
```