

Huawei Access Switch Alarm SOP - ALARM_7471

Note: Huawei-Access-Chennai-TN-84 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_7471

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_7471, a major alarm on the Huawei-Access-Chennai-TN-84 access switch.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software bug or configuration issue	Medium
Environmental factors such as power issues or temperature fluctuations	Low

Diagnostic Commands

```
display current-connection
display interface
display error
debug switchtree
```

Resolution Steps

- Step 1: {'Step': 'Check the switch logs for any error messages', 'Action': 'Run the command: display error'}
- Step 2: {'Step': 'Verify the switch connections', 'Action': 'Run the command: display current-connection'}
- Step 3: {'Step': 'Inspect the switch hardware for any physical damage or issues', 'Action': 'Perform a visual inspection of the switch'}
- Step 4: {'Step': 'Run a software version check and update if necessary', 'Action': 'Run the command: display version'}
- Step 5: {'Step': 'Reset the switch to its default configuration', 'Action': 'Run the command: reset'}

Post-Check Verification

```
display interface
display error
display current-connection
```