

Huawei Access Switch Alarm SOP: ALARM_3163

Node: Huawei-Access-Chennai-TN-92 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_3163

Description

The Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-92 has triggered a minor alarm with alarm code ALARM_3163. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
High CPU utilization due to software issues	High
Interface congestion or misconfiguration	Medium
Hardware issues with the Access Switch	Low

Diagnostic Commands

```
display current-configuration
display cpu-usage
display interface brief
display mac-address-table
```

Resolution Steps

Step 1: {'Step': 'Run the command "display cpu-usage" to check the CPU utilization. If the CPU utilization is high, proceed to the next step.', 'Action': 'Restart the Access Switch to clear the software issues.'}

Step 2: {'Step': 'Run the command "display interface brief" to check the interface status. If the interface is congested or misconfigured, proceed to the next step.', 'Action': 'Configure the interface to improve the link quality using the command "interface , description , bandwidth ""}

Step 3: {'Step': 'Run the command "display mac-address-table" to check the MAC address table. If there are any issues with the MAC address table, proceed to the next step.', 'Action': 'Clear the MAC address table using the command "clear mac-address-table"}

Post-Check Verification

```
display cpu-usage
display interface brief
display mac-address-table
```