

Huawei Access Switch Alarm 1985 Resolution SOP

Node: Huawei-Access-Chennai-TN-94 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_1985

Description

This SOP outlines the step-by-step process to diagnose, resolve, and verify the fix for Huawei Access Switch alarm ALARM_1985 (Severity: Minor) on Node ID Huawei-Access-Chennai-TN-94.

Potential Root Causes

Cause	Probability
Misconfigured VLAN settings	High
Port malfunction due to hardware failure	Medium
Spanning Tree Protocol (STP) loop	Low

Diagnostic Commands

```
display version
display vlan
display interface
debug stp
```

Resolution Steps

- Step 1: {'Step': '1. Check VLAN configuration', 'Action': "Run 'display vlan' command and verify VLAN settings.", 'CLI_Command': 'display vlan'}
- Step 2: {'Step': '2. Check port status', 'Action': "Run 'display interface' command and verify port status.", 'CLI_Command': 'display interface'}
- Step 3: {'Step': '3. Check STP status', 'Action': "Run 'debug stp' command and verify STP status.", 'CLI_Command': 'debug stp'}
- Step 4: {'Step': '4. Reboot the switch (if necessary)', 'Action': "Run 'reboot' command to reboot the switch.", 'CLI_Command': 'reboot'}

Post-Check Verification

```
display version
display vlan
display interface
debug stp
```