

Huawei Access Switch Alarm Resolution SOP for ALARM_6825

Node: Huawei-Access-Chennai-TN-94 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_6825

Description

This SOP outlines the steps to diagnose and resolve the ALARM_6825 (Minor) on Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-94.

Potential Root Causes

Cause	Probability
Link aggregation protocol (LACP) mismatch between the access switch and the neighboring device.	High
Invalid or misconfigured LACP settings on the access switch.	Medium
Physical fiber issues or connectivity problems between the access switch and the neighboring device.	Low

Diagnostic Commands

```
display lacp neighbor
display lacp system
display interface GigabitEthernet 0/0/1
display fiber info GigabitEthernet 0/0/1
```

Resolution Steps

- Step 1: {'Step': 'Verify LACP settings on the access switch.', 'Action': 'Check and configure LACP settings as per the neighboring device.'}
- Step 2: {'Step': 'Check LACP neighbor status.', 'Action': "Run the command 'display lacp neighbor' to verify LACP neighbor status."}
- Step 3: {'Step': 'Verify physical fiber connectivity.', 'Action': "Run the command 'display fiber info GigabitEthernet 0/0/1' to verify physical fiber connectivity."}
- Step 4: {'Step': 'Reset LACP protocol.', 'Action': "Run the command 'reset lacp' to reset LACP protocol on the access switch."}

Post-Check Verification

```
display lacp system
display lacp neighbor
```

```
display interface GigabitEthernet 0/0/1  
display fiber info GigabitEthernet 0/0/1
```