

Huawei Access Switch Alarm SOP

Node: Huawei-Access-Chennai-TN-94 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_7546

Description

Alarm Code: ALARM_7546 - Warning Severity on Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-94

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software bug in the switch's firmware	Medium
Environmental factors affecting the switch	Low

Diagnostic Commands

```
display version
display diagnostics result
diag monitor board fault
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch', 'Action': "Use the command 'shutdown' to shut down the switch, wait for 30 seconds, and then use the command 'reset' to power it back on."}
- Step 2: {'Step': "Check the switch's firmware version", 'Action': "Use the command 'display version' to verify the current firmware version. If it's outdated, update it to the latest version using the command 'install software package'."}
- Step 3: {'Step': 'Reset the switch to its default settings', 'Action': "Use the command 'reset system' to reset the switch to its default settings."}
- Step 4: {'Step': "Verify the switch's health", 'Action': "Use the command 'display diagnostics result' to verify the switch's health."}

Post-Check Verification

```
display version
display diagnostics result
diag monitor board fault
```