

Huawei Access Switch - ALARM_6001 (Major) - Root Cause Analysis and Resolution

Node: Huawei-Access-Delhi-NCR-16 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_6001

Description

This SOP outlines the process for identifying and resolving the ALARM_6001 (Major) on the Huawei Access Switch node Huawei-Access-Delhi-NCR-16. The alarm is triggered due to a hardware or software issue that affects the switch's ability to function correctly.

Potential Root Causes

Cause	Probability
Hardware failure of the switch's power supply unit (PSU)	High
Software issue with the switch's operating system (OS) or firmware	Medium
Electrical surge or power fluctuation affecting the switch	Low

Diagnostic Commands

```
display version
display diagnose eeprom
display error
display power supply
```

Resolution Steps

Step 1: {'Step': "1. Check the switch's power supply unit (PSU)", 'Action': 'Enter the command **display power supply** to check the status of the PSU.'}

Step 2: {'Step': "2. Check the switch's software version", 'Action': "Enter the command **display version** to check the switch's software version."}

Step 3: {'Step': "3. Check the switch's EEPROM for any issues", 'Action': "Enter the command **display diagnose eeprom** to check the switch's EEPROM for any issues."}

Step 4: {'Step': "4. Check the switch's error logs for any critical errors", 'Action': "Enter the command **display error** to check the switch's error logs for any critical errors."}

Step 5: {'Step': "5. Replace the faulty PSU or update the switch's software/firmware as necessary", 'Action': "Replace the faulty PSU or update the switch's software/firmware as necessary to resolve the issue."}

Post-Check Verification

```
display version  
display diagnose eeprom  
display error  
display power supply
```