

Huawei Access Switch Alarm SOP: ALARM_1626 (Warning)

Node: Huawei-Access-Delhi-NCR-24 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_1626

Description

This SOP covers the diagnostic, resolution, and verification steps for the Huawei Access Switch alarm ALARM_1626 with a severity of Warning.

Potential Root Causes

Cause	Probability
High CPU Utilization on the Access Switch	High
Excessive Packets in the Buffer	Medium
Misconfigured Quality of Service (QoS)	Low

Diagnostic Commands

```
display cpu utilization
display buffer packet
display qos configuration
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Check CPU Utilization', 'Action': "Check the CPU utilization of the Access Switch using the command 'display cpu utilization'. If CPU utilization is high, proceed to the next step.", 'CLI_Command': 'display cpu utilization'}
- Step 2: {'Step': 'Step 2: Clear Buffer Packets', 'Action': "Clear excessive packets in the buffer using the command 'clear buffer packet'. Then, verify if the issue is resolved.", 'CLI_Command': 'clear buffer packet'}
- Step 3: {'Step': 'Step 3: Reconfigure QoS', 'Action': "Reconfigure the Quality of Service (QoS) settings on the Access Switch using the command 'qos configuration'. Then, verify if the issue is resolved.", 'CLI_Command': 'qos configuration'}

Post-Check Verification

```
display cpu utilization
display buffer packet
display qos configuration
```