

Standard Operating Procedure for Resolving Huawei Access Switch Alarm ALARM_6159

Node: Huawei-Access-Kolkata-WB-112 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_6159

Description

Alarm ALARM_6159 on Huawei-Access-Kolkata-WB-112 indicates a critical issue.

Potential Root Causes

Cause	Probability
Hardware failure in the uplink module.	High
Misconfigured uplink settings.	Medium
Software issues with the access switch.	Low

Diagnostic Commands

```
display version
display diagnostic result uplink-module
display interface uplink-module
show run | include uplink-settings
```

Resolution Steps

Step 1: {'Step': 'Replace the faulty uplink module.', 'Action': "Use the command 'replace uplink-module' to initiate the replacement process.", 'Precaution': 'Ensure the module is replaced in a redundant configuration to avoid service disruption.'}

Step 2: {'Step': 'Verify uplink configuration.', 'Action': "Check the uplink settings using 'show run | include uplink-settings' and correct any misconfigurations.", 'Precaution': 'Restart the access switch after making changes to the uplink settings.'}

Step 3: {'Step': 'Upgrade access switch software.', 'Action': "Use the command 'upgrade software' to initiate the software upgrade process.", 'Precaution': 'Schedule the upgrade during maintenance windows to avoid service disruption.'}

Post-Check Verification

```
display diagnostic result uplink-module
display interface uplink-module
show ip interface brief
```

```
show run | include uplink-settings
```