

Huawei Access Switch Alarm Handling SOP -

ALARM_4759: Warning

Node: Huawei-Access-Kolkata-WB-132 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_4759

Description

This SOP outlines the steps to diagnose, resolve and verify the fix for ALARM_4759: Warning on Huawei Access Switch (Node ID: Huawei-Access-Kolkata-WB-132). The alarm indicates a potential issue with the switch's configuration or hardware.

Potential Root Causes

Cause	Probability
Invalid VLAN configuration	High
Hardware failure in the switch's CPU or fan module	Medium
Software issues with the switch's firmware or configuration files	Low

Diagnostic Commands

```
display this
display version
display vlan
display interface
display error-enable
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Check VLAN configuration', 'Action': "Verify VLAN configuration using 'display vlan' command"}
- Step 2: {'Step': 'Step 2: Check for hardware failures', 'Action': "Run 'display hardware' command to check for any hardware issues"}
- Step 3: {'Step': 'Step 3: Update firmware or configuration files', 'Action': "Update firmware or configuration files using 'upgrade' command"}
- Step 4: {'Step': 'Step 4: Restart the switch', 'Action': "Restart the switch using 'reload' command"}

Post-Check Verification

```
display vlan
```

```
display interface
display error-enable
display version
```