

Huawei Access Switch Alarm Handling SOP

(ALARM_8904)

Node: Huawei-Access-Mumbai-MH-42 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_8904

Description

This SOP outlines the procedures for handling the ALARM_8904 on the Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-42.

Potential Root Causes

Cause	Probability
Incorrectly configured Layer 2 protocol tunnel (L2PT)	High
Misconfigured VLAN mappings	Medium
Faulty or malfunctioning switch hardware	Low

Diagnostic Commands

```
display current-configuration | include l2pt
display vlan mapping
display device internal-debugging information
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Verify L2PT configuration and correct if necessary', 'CLI_Command': 'undo l2pt'}
- Step 2: {'Step': 2, 'Action': 'Verify VLAN mappings and correct if necessary', 'CLI_Command': 'undo vlan mapping'}
- Step 3: {'Step': 3, 'Action': 'Replace faulty or malfunctioning hardware if necessary', 'CLI_Command': ''}

Post-Check Verification

```
display current-configuration | include l2pt
display vlan mapping
display device internal-debugging information
```