

Huawei Access Switch SOP for ALARM_8590

Node: Huawei-Access-Mumbai-MH-48 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_8590

Description

This SOP outlines the steps to diagnose and resolve the ALARM_8590 issue on the Huawei Access Switch, Node ID: Huawei-Access-Mumbai-MH-48.

Potential Root Causes

Cause	Probability
Incorrect configuration of the storm-control feature	High
Hardware failure of the switch or interface	Medium
Software bug or incompatibility	Low

Diagnostic Commands

```
display storm-control
display interface GigabitEthernet 0/0/1 status
display version
```

Resolution Steps

- Step 1: {'Step': 'Check the storm-control configuration', 'Action': "Use the command 'display storm-control' to verify the configuration and compare it with the design specifications.", 'CLI_Command': 'display storm-control'}
- Step 2: {'Step': 'Verify the interface status', 'Action': "Use the command 'display interface GigabitEthernet 0/0/1 status' to verify the interface status and look for any errors or warnings.", 'CLI_Command': 'display interface GigabitEthernet 0/0/1 status'}
- Step 3: {'Step': 'Upgrade the software or replace the hardware', 'Action': 'If the issue persists, consider upgrading the software or replacing the hardware, depending on the root cause identified.', 'CLI_Command': 'upgrade package'}

Post-Check Verification

```
display storm-control
display interface GigabitEthernet 0/0/1 status
display version
```