

Huawei Access Switch - Alarm Resolution SOP for ALARM_5490

Node: Huawei-Access-Mumbai-MH-50 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_5490

Description

Minor alarm triggered on Huawei-Access-Mumbai-MH-50 Access Switch due to potential configuration or software issue.

Potential Root Causes

Cause	Probability
Incorrect VLAN configuration	High
Faulty network interface	Medium
Software glitch or bug	Low

Diagnostic Commands

```
display version
display vlan
display interface
debug enable
debug interface
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': 'Check VLAN configuration using display vlan command and compare with expected settings.', 'CLI_Command': 'display vlan'}
- Step 2: {'Step': 'Replace faulty network interface', 'Action': 'Swap the faulty interface with a spare one and reboot the switch.', 'CLI_Command': 'replace interface '}
- Step 3: {'Step': 'Upgrade software or apply patch', 'Action': 'Check for and apply software updates or patches to resolve the issue.', 'CLI_Command': 'software install '}

Post-Check Verification

```
display version
display vlan
display interface
```

ping