

Huawei Access Switch Alarm Handling Procedure - ALARM_6549

Node: Huawei-Access-Mumbai-MH-50 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_6549

Description

Minor alarm on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-50 indicating potential issue with switch operations.

Potential Root Causes

Cause	Probability
Switch Software Bug	Medium
Misconfigured Switch Ports	High
Hardware Fault (e.g. Fan, Power Supply)	Low

Diagnostic Commands

```
display current-configuration
display interface brief
display cpu-memory-usage
display system info
display alarm info
```

Resolution Steps

- Step 1: {'Step': 'Verify switch software version and check for any available updates.', 'Action': "check for software updates using 'display version' command"}
- Step 2: {'Step': 'Verify switch port configurations and make necessary adjustments.', 'Action': "use 'display interface brief' command to verify port configurations and make changes as needed"}
- Step 3: {'Step': 'Check for hardware issues (e.g. fan, power supply) and replace if necessary.', 'Action': "use 'display system info' command to check for hardware issues and replace if necessary"}
- Step 4: {'Step': "Clear alarm using 'clear alarm' command.", 'Action': "use 'clear alarm' command to clear the alarm"}

Post-Check Verification

```
display current-configuration
```

```
display interface brief
display cpu-memory-usage
display system info
display alarm info
```