

Huawei Access Switch - Alarm Resolution SOP for Node ID: Huawei-Access-Mumbai-MH-50

Node: Huawei-Access-Mumbai-MH-50 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_7276

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for the ALARM_7276 (Warning) on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-50.

Potential Root Causes

Cause	Probability
Optical interface issue	High
Cable or optical fiber damage	Medium
Misconfigured port settings	Low

Diagnostic Commands

```
display interface
display optical interface
display link
display interface statistics
```

Resolution Steps

- Step 1: {'Step': '1. Check the optical interface status', 'Action': 'Run the command "display optical interface" to verify the optical interface status.', 'CLI_Command': 'display optical interface'}
- Step 2: {'Step': '2. Verify the cable or optical fiber', 'Action': 'Inspect the cable or optical fiber for any signs of damage.', 'CLI_Command': ''}
- Step 3: {'Step': '3. Check the port settings', 'Action': 'Run the command "display interface" to verify the port settings.', 'CLI_Command': 'display interface'}
- Step 4: {'Step': '4. Reset the interface', 'Action': 'Run the command "reset interface" to reset the interface.', 'CLI_Command': 'reset interface'}

Post-Check Verification

```
display interface
display optical interface
```

```
display link  
display interface statistics
```