

Huawei Access Switch Alarm Troubleshooting SOP for ALARM_9189

Node: Huawei-Access-Mumbai-MH-50 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_9189

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_9189 on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-50. The alarm indicates a major issue and requires immediate attention.

Potential Root Causes

Cause	Probability
Hardware failure in the switch or its components	High
Software bug or misconfiguration	Medium
Environmental issues such as power outages or temperature fluctuations	Low

Diagnostic Commands

```
display version
display cpu usage
display memory usage
display interface brief
```

Resolution Steps

- Step 1: {'Step': 'Run diagnostic commands to identify potential issues', 'Description': "Verify the switch's software and hardware versions, CPU usage, memory usage, and interface status."}
- Step 2: {'Step': 'Check for software bugs or misconfigurations', 'Description': "Verify the switch's configuration, including VLANs, VRFs, and ACLs. Check for any recent software upgrades or changes.", 'Command': 'display current-configuration'}
- Step 3: {'Step': 'Perform hardware checks', 'Description': "Verify the switch's hardware components, including fans, power supplies, and interfaces. Check for any signs of physical damage or wear.", 'Command': 'display hardware'}
- Step 4: {'Step': 'Resolve the issue', 'Description': 'Based on the findings, resolve the issue by replacing faulty hardware, updating software, or correcting misconfigurations.'}

Post-Check Verification

```
display version
display cpu usage
display memory usage
display interface brief
```