

Huawei Access Switch Node Mumbai-MH-56 Alarm SOP (ALARM_3431)

Node: Huawei-Access-Mumbai-MH-56 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_3431

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_3431 on the Huawei Access Switch Node Mumbai-MH-56. The alarm indicates a warning condition.

Potential Root Causes

Cause	Probability
Incorrect VLAN configuration	High
Faulty network interface	Medium
Switch software issues	Low

Diagnostic Commands

```
display current-configuration | include vlan
display interface | include Admin-Down
display version
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': "Run the command 'display current-configuration | include vlan' to check the VLAN configuration.", 'CLI_Command': 'display current-configuration | include vlan'}
- Step 2: {'Step': 'Check network interface status', 'Action': "Run the command 'display interface | include Admin-Down' to verify the network interface status.", 'CLI_Command': 'display interface | include Admin-Down'}
- Step 3: {'Step': 'Upgrade switch software', 'Action': 'Download and upgrade the switch software to the latest version.', 'CLI_Command': 'system-view\ncopy ftp:// system/software \nupgrade system'}

Post-Check Verification

```
display current-configuration | include vlan
display interface | include Admin-Down
display version
```