

Huawei Access Switch SOP: Alarm Code

ALARM_3752

Node: Huawei-Access-Mumbai-MH-56 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_3752

Description

This SOP outlines the step-by-step process for resolving the Huawei Access Switch Alarm Code ALARM_3752, a minor alarm indicating a potential issue with the switch.

Potential Root Causes

Cause	Probability
Incorrect configuration or inconsistencies in the switch's database	Medium
Hardware or software compatibility issues	Low
Environmental or power issues affecting the switch	Low

Diagnostic Commands

```
display current-configuration | include interface
display version
display cpu-usage
display memory-usage
```

Resolution Steps

- Step 1: {'Step': 'Collect switch logs and system information for analysis', 'Action': "Use the command 'display log' to collect logs and 'display system-internal info' to gather system information."}
- Step 2: {'Step': 'Verify switch configuration for inconsistencies', 'Action': "Use the command 'display current-configuration | include interface' to verify switch configuration."}
- Step 3: {'Step': "Reboot the switch in 'maintenance mode'", 'Action': "Use the command 'maintain reboot' to reboot the switch in maintenance mode."}
- Step 4: {'Step': 'Verify the issue is resolved', 'Action': "Use the command 'display cpu-usage' and 'display memory-usage' to verify the issue is resolved."}
- Step 5: {'Step': 'Update the switch firmware to the latest version', 'Action': "Use the command 'system update' to update the switch firmware."}

Post-Check Verification

```
display cpu-usage  
display memory-usage  
display interface statistics
```