

Huawei Access Switch ALARM_9910 SOP

Node: Huawei-Access-Mumbai-MH-56 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_9910

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose, resolve, and verify the fix for Major Alarm ALARM_9910 on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-56.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Optical Fiber Damage	Medium
Software Bug	Low

Diagnostic Commands

```
display current-configuration
display interface status
display optic-fiber status
display error-message
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the access switch', 'Action': 'power-off', 'CLI_Command': 'shutdown', 'Description': 'Power cycle the access switch to reset the system.'}
- Step 2: {'Step': '2. Inspect the optical fibers for damage', 'Action': 'Verify the integrity of the optical fibers', 'CLI_Command': '', 'Description': 'Inspect the optical fibers for any signs of damage or wear.'}
- Step 3: {'Step': '3. Update the software to the latest version', 'Action': 'Update the software', 'CLI_Command': 'system sw download', 'Description': 'Update the software to the latest version to fix any known bugs.'}
- Step 4: {'Step': '4. Replace the faulty hardware component', 'Action': 'Replace the faulty hardware', 'CLI_Command': '', 'Description': 'Replace the faulty hardware component with a new one.'}

Post-Check Verification

```
display current-configuration
display interface status
display optic-fiber status
```

```
display error-message
```