

Huawei PE Router Alarm SOP - ALARM_7558

Node: Huawei-PE-Chennai-TN-93 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_7558

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7558 (Critical) issue on Huawei PE Router Node ID: Huawei-PE-Chennai-TN-93.

Potential Root Causes

Cause	Probability
High CPU Utilization on Routing Engine	High
Misconfiguration of Routing Protocol	Medium
Hardware Failure	Low

Diagnostic Commands

```
display this
debug cpu
show routing protocol
show bgp summary
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Description': "Run the command 'display cpu | include CPU%' to check the CPU utilization.", 'Action': 'Monitor CPU utilization and take necessary actions to reduce it.'}
- Step 2: {'Step': '2. Verify Routing Protocol Configuration', 'Description': "Run the command 'show routing protocol' to verify the routing protocol configuration.", 'Action': 'Correct any misconfiguration and reapply the changes.'}
- Step 3: {'Step': '3. Check Hardware Status', 'Description': "Run the command 'display hardware | include Status' to check the hardware status.", 'Action': 'Replace the faulty hardware if necessary.'}
- Step 4: {'Step': '4. Clear BGP Sessions', 'Description': "Run the command 'clear bgp *' to clear the BGP sessions.", 'Action': 'Verify that the BGP sessions are established after clearing.'}

Post-Check Verification

```
display bgp summary
show ip bgp | include Established
show cpu | include CPU%
```