

Huawei Provider Edge Router (PE) Alarm Resolution SOP

Node: Huawei-PE-Chennai-TN-93 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_7600

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the Huawei ALARM_7600 alarm on the Provider Edge Router (PE) located at Chennai, TN-93.

Potential Root Causes

Cause	Probability
High CPU usage due to excessive routing updates.	High
Misconfiguration of routing protocols.	Medium
Hardware issues such as faulty interface cards or memory problems.	Low

Diagnostic Commands

```
display cpu usage
display routing-table
display routing-protocol
display interface
display board
```

Resolution Steps

- Step 1: {'Step': 'Check CPU usage and routing table for inconsistencies.', 'Action': "Use the 'display cpu usage' and 'display routing-table' commands to identify if the CPU is utilized above 80% and if there are any inconsistencies in the routing table."}
- Step 2: {'Step': 'Verify routing protocol configuration.', 'Action': "Use the 'display routing-protocol' command to verify if the routing protocol configuration is correct and if it matches the vendor's recommendations."}
- Step 3: {'Step': 'Replace faulty hardware if identified.', 'Action': "Use the 'display board' command to identify faulty interface cards or memory problems and replace them with new ones."}
- Step 4: {'Step': 'Reset the router to its factory default settings.', 'Action': "Use the 'reset' command to reset the router to its factory default settings and reconfigure it from scratch."}

Post-Check Verification

```
display cpu usage  
display routing-table  
display routing-protocol  
display interface  
display board
```