

Huawei Provider Edge Router Alarm Resolution SOP

Node: Huawei-PE-Chennai-TN-93 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_8585

Description

This procedure outlines the steps to resolve the ALARM_8585 on Huawei-PE-Chennai-TN-93, a Provider Edge Router.

Potential Root Causes

Cause	Probability
Misconfigured BGP peer	High
Interface flapping	Medium
Software bug	Low

Diagnostic Commands

```
display bgp peer-status
display interface brief
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP peer configuration', 'Action': 'Verify the BGP peer configuration using display bgp peer-status command'}
- Step 2: {'Step': 'Check interface status', 'Action': 'Check the interface status using display interface brief command'}
- Step 3: {'Step': 'Reboot the router', 'Action': 'Reboot the router if software bug is suspected'}
- Step 4: {'Step': 'Upgrade the software', 'Action': 'Upgrade the software to the latest version if software bug is suspected'}

Post-Check Verification

```
display bgp peer-status
display interface brief
show tech-support
```