

SOP for Huawei Provider Edge Router ALARM_5182 in Mumbai

Node: Huawei-PE-Mumbai-MH-57 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_5182

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the ALARM_5182 warning on Huawei Provider Edge Router (Huawei-PE-Mumbai-MH-57) in Mumbai.

Potential Root Causes

Cause	Probability
BGP session failure due to routing policy mismatch	High
Interface flap due to hardware or software issues	Medium
Misconfigured BGP peer	Low

Diagnostic Commands

```
display bgp peer all
display interface brief
display bgp vpnv4 all
show bgp summary
show bgp neighbors
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP session status', 'Action': 'Run command: display bgp peer all'}
- Step 2: {'Step': 'Check for routing policy mismatch', 'Action': 'Run command: display bgp vpnv4 all'}
- Step 3: {'Step': 'Check interface status', 'Action': 'Run command: display interface brief'}
- Step 4: {'Step': 'Reset BGP peer', 'Action': 'Use command: reset bgp peer soft-in soft-out'}
- Step 5: {'Step': 'Verify BGP session status after reset', 'Action': 'Run command: display bgp peer all'}

Post-Check Verification

```
display bgp peer all
display interface brief
display bgp vpnv4 all
```

```
show bgp summary  
show bgp neighbors
```