

Huawei Provider Edge Router (PE) Alarm

Troubleshooting: ALARM_5432

Node: Huawei-PE-Mumbai-MH-57 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_5432

Description

Minor alarm on Huawei PE device Huawei-PE-Mumbai-MH-57 due to unidentified cause.

Potential Root Causes

Cause	Probability
Invalid or Misconfigured BGP Neighbor	Medium
Incorrect or Missing OSPF Configuration	Low
Software or Hardware Issue with the PE Device	Low

Diagnostic Commands

```
display current-configuration | include bgp neighbor
display bgp vpnv4 all summary
display ospf interface brief
display device hardware verbose
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP neighbor configuration and ensure it is correct.', 'Action': 'Verify BGP neighbor configuration using display current-configuration | include bgp neighbor command.\n'}
- Step 2: {'Step': 'Verify OSPF configuration and ensure it is correct.', 'Action': 'Verify OSPF configuration using display current-configuration | include ospf command.\n'}
- Step 3: {'Step': 'Restart BGP and OSPF processes.', 'Action': 'admin restart bgp\nadmin restart ospf\n'}
- Step 4: {'Step': 'Check for software or hardware issues with the PE device.', 'Action': 'Check device logs and perform hardware checks if necessary.\n'}

Post-Check Verification

```
display bgp vpnv4 all summary
display ospf interface brief
display device hardware verbose
```