

Huawei PE Router Alarm Resolution SOP

Node: Huawei-PE-Mumbai-MH-57 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_9509

Description

Resolving Huawei Provider Edge Router (PE) critical alarm ALARM_9509

Potential Root Causes

Cause	Probability
Hardware failure on the PE router	High
Software configuration issue on the PE router	Medium
Network connectivity issue between the PE router and the upstream provider	Low

Diagnostic Commands

```
show alarm current
show interface brief
show ip int br
show bgp summary
show mpls ldp neighbor detail
```

Resolution Steps

- Step 1: {'Step': 'Reload the PE router', 'Action': 'reload in 5'}
- Step 2: {'Step': 'Verify hardware failure', 'Action': 'show alarm history'}
- Step 3: {'Step': 'Check and adjust software configuration', 'Action': 'show running-config | include bgp'}
- Step 4: {'Step': 'Verify network connectivity', 'Action': 'ping '}
- Step 5: {'Step': 'Clear BGP sessions', 'Action': 'clear bgp '}
- Step 6: {'Step': 'Verify LDP sessions', 'Action': 'show mpls ldp neighbor detail'}

Post-Check Verification

```
show alarm current
show interface brief
show ip int br
show bgp summary
show mpls ldp neighbor detail
```