

Juniper Core Router SOP for ALARM_1131: Critical Alarm on Juniper-Core-Chennai-TN-1

Node: Juniper-Core-Chennai-TN-1 | **Vendor:** Juniper | **Severity:** Critical | **Alarm Code:** ALARM_1131

Description

ALARM_1131 is a Critical alarm indicating a hardware failure or a software issue on the Juniper Core Router. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Issue	Medium
Configuration Error	Low

Diagnostic Commands

```
show chassis hardware
show system resources
show interfaces extensive
```

Resolution Steps

- Step 1: {'Step': '1. Inspect the hardware', 'Action': 'Physically inspect the router to identify any visible signs of hardware failure.'}
- Step 2: {'Step': '2. Run diagnostic tests', 'Action': '"Use the 'test' command to run diagnostic tests on the router's hardware and software.'}"}
- Step 3: {'Step': '3. Reboot the router', 'Action': 'Reboot the router to see if the issue resolves itself.'}
- Step 4: {'Step': '4. Check the logs', 'Action': 'Check the system logs to see if there are any error messages related to the alarm.'}
- Step 5: {'Step': '5. Replace the faulty component', 'Action': 'If the issue is hardware-related, replace the faulty component and reboot the router.'}

Post-Check Verification

```
show chassis hardware
show system resources
show interfaces extensive
```

show log messages