

Juniper Core Router Alarm SOP for ALARM_2055

Node: Juniper-Core-Chennai-TN-1 | **Vendor:** Juniper | **Severity:** Minor | **Alarm Code:** ALARM_2055

Description

Alarm ALARM_2055 on Juniper Core Router Juniper-Core-Chennai-TN-1 indicates a minor issue. The purpose of this SOP is to troubleshoot and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured OSPF settings	Medium
Hardware failure in the router	Low
Software bug in the Junos OS	Low

Diagnostic Commands

```
show ospf neighbor
show ospf database
show chassis hardware
show system uptime
show version
```

Resolution Steps

Step 1: {'Step': 'Verify OSPF neighbor relationships', 'Action': "Run the command 'show ospf neighbor' to ensure all neighbors are up and reachable."}

Step 2: {'Step': 'Check OSPF database for inconsistencies', 'Action': "Run the command 'show ospf database' to verify that the OSPF database is consistent across all routers."}

Step 3: {'Step': 'Inspect router hardware for issues', 'Action': "Run the command 'show chassis hardware' to verify that all hardware components are functioning correctly."}

Step 4: {'Step': 'Verify system uptime and software version', 'Action': "Run the command 'show system uptime' to verify that the system has not crashed recently, and 'show version' to ensure the Junos OS is up-to-date."}

Step 5: {'Step': 'Clear OSPF database and restart OSPF process', 'Action': "Run the command 'clear ospf database' and then 'request system reboot' to restart the OSPF process."}

Step 6: {'Step': 'Verify OSPF neighbor relationships after reboot', 'Action': "Run the command 'show ospf neighbor' after the reboot to verify that the OSPF neighbor relationships have been restored."}

Post-Check Verification

```
show ospf neighbor  
show ospf database  
show chassis hardware  
show system uptime
```