

Juniper Core Router Minor Alarm SOP - ALARM_7220

Node: Juniper-Core-Chennai-TN-1 | **Vendor:** Juniper | **Severity:** Minor | **Alarm Code:** ALARM_7220

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for the ALARM_7220 (Minor) on the Juniper Core Router Node ID: Juniper-Core-Chennai-TN-1.

Potential Root Causes

Cause	Probability
Misconfigured routing protocol parameters	High
Inconsistent routing table entries	Medium
Hardware or software failure	Low

Diagnostic Commands

```
show bgp summary
show route summary
show chassis hardware
show system uptime
```

Resolution Steps

Step 1: {'Step': '1. Check and configure routing protocol parameters', 'Action': "Configure routing protocol parameters using the 'set protocols bgp ' command"}

Step 2: {'Step': '2. Verify routing table consistency', 'Action': "Run the 'show route summary' command to verify routing table consistency"}

Step 3: {'Step': '3. Replace or repair hardware if necessary', 'Action': "Replace or repair hardware if the 'show chassis hardware' command indicates a hardware failure"}

Step 4: {'Step': '4. Upgrade or patch software if necessary', 'Action': "Upgrade or patch software if the 'show system uptime' command indicates a software issue"}

Post-Check Verification

```
show bgp summary
show route summary
show chassis hardware
```

```
show system uptime
```