

Juniper Core Router SOP for Alarm Code

ALARM_3203

Node: Juniper-Core-Mumbai-MH-1 | **Vendor:** Juniper | **Severity:** Minor | **Alarm Code:** ALARM_3203

Description

Alarm Code ALARM_3203 is related to 'FPC not present or failed' on Juniper Core Router Node ID: Juniper-Core-Mumbai-MH-1

Potential Root Causes

Cause	Probability
FPC not present or failed	High
Faulty FPC card	Medium
Incorrect FPC configuration	Low

Diagnostic Commands

```
show chassis hardware
show chassis environment
show chassis fpc
show fpc statistics
```

Resolution Steps

- Step 1: {'Step': 'Check the FPC status', 'Action': "execute command 'show chassis hardware' and verify the FPC status", 'Command': 'show chassis hardware'}
- Step 2: {'Step': "Replace the FPC card if it's faulty", 'Action': "replace the FPC card with a new one and verify the status using 'show chassis hardware' command", 'Command': 'request system software add fpc '}
- Step 3: {'Step': 'Verify the FPC configuration', 'Action': "check the FPC configuration using 'show chassis fpc' command and correct it if necessary", 'Command': 'show chassis fpc'}

Post-Check Verification

```
show chassis hardware
show chassis fpc
```