

Juniper Core Router SOP for Alarm Code

ALARM_4079

Node: Juniper-Core-Mumbai-MH-1 | **Vendor:** Juniper | **Severity:** Major | **Alarm Code:** ALARM_4079

Description

Alarm Code ALARM_4079 indicates a major issue on Juniper Core Router Juniper-Core-Mumbai-MH-1. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured Routing Protocol	High
Hardware Failure in Routing Engine	Medium
Software Bug in Routing Protocol	Low

Diagnostic Commands

```
show version
show chassis hardware
show routing-engine
show routing-options
show protocols
```

Resolution Steps

Step 1: {'Step': '1. Check Routing Protocol Configuration', 'Action': "Verify routing protocol configuration using command 'show routing-options'. Compare with the expected configuration."}

Step 2: {'Step': '2. Check Routing Engine Health', 'Action': "Verify routing engine health using command 'show chassis hardware'. Check for any hardware failure."}

Step 3: {'Step': '3. Check Software Version', 'Action': "Verify software version using command 'show version'. Check for any software updates."}

Step 4: {'Step': '4. Reboot Routing Engine', 'Action': "Reboot the routing engine using command 'request system reboot'."}

Step 5: {'Step': '5. Verify Resolution', 'Action': "Verify the issue is resolved using command 'show version' and 'show chassis hardware'."}

Post-Check Verification

```
show version
show chassis hardware
show routing-options
show protocols
```