

Troubleshooting Juniper Provider Edge Router (PE) ALARM_5250 on Juniper-PE-Chennai-TN-105

Node: Juniper-PE-Chennai-TN-105 | **Vendor:** Juniper | **Severity:** Major | **Alarm Code:** ALARM_5250

Description

ALARM_5250 is triggered when a major issue occurs on the Juniper Provider Edge Router (PE) with Node ID: Juniper-PE-Chennai-TN-105. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured BGP neighbor	High
Hardware failure of the line card	Medium
Misconfigured routing policy	Low

Diagnostic Commands

```
show bgp summary
show bgp neighbors
show routing-table detail
show chassis hardware
show system info
```

Resolution Steps

- Step 1: {'Step': '1. Check BGP neighbor configuration', 'Action': "Run 'show bgp summary' and 'show bgp neighbors' commands to verify BGP neighbor configuration"}
- Step 2: {'Step': '2. Check routing policy configuration', 'Action': "Run 'show routing-table detail' command to verify routing policy configuration"}
- Step 3: {'Step': '3. Check line card status', 'Action': "Run 'show chassis hardware' command to check line card status"}
- Step 4: {'Step': '4. Replace failed line card (if applicable)', 'Action': 'Replace the failed line card with a new one and verify the issue is resolved'}
- Step 5: {'Step': '5. Verify BGP neighbor configuration', 'Action': "Run 'set protocols bgp group neighbor remote-as ' command to configure BGP neighbor"}

Post-Check Verification

```
show bgp summary
show bgp neighbors
show routing-table detail
```