

SOP for Resolving Juniper Provider Edge Router (PE) Alarm ALARM_4135

Node: Juniper-PE-Chennai-TN-95 | **Vendor:** Juniper | **Severity:** Critical | **Alarm Code:** ALARM_4135

Description

Alarm ALARM_4135 indicates a critical issue on the Juniper Provider Edge Router (PE) Juniper-PE-Chennai-TN-95. This SOP outlines the necessary steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Interface flapping due to hardware or software issues	High
Misconfigured routing protocols	Medium
Physical or environmental issues affecting the router's operation	Low

Diagnostic Commands

```
show chassis hardware
show interfaces detail | match ALARM_4135
show routing-table | match ALARM_4135
```

Resolution Steps

- Step 1: {'Step': "1. Check the router's hardware and software configuration for any errors or issues.", 'Action': "Run the 'show chassis hardware' command to verify the router's hardware configuration."}
- Step 2: {'Step': "2. Verify the interface configuration and status.", 'Action': "Run the 'show interfaces detail' command to verify the interface configuration and status."}
- Step 3: {'Step': "3. Review and update the routing protocol configuration as necessary.", 'Action': "Run the 'show routing-table' command to verify the routing protocol configuration."}
- Step 4: {'Step': "4. Check the router's logs for any errors or issues.", 'Action': "Run the 'show log' command to verify the router's logs."}
- Step 5: {'Step': "5. If the issue persists, restart the router.", 'Action': "Run the 'request system reboot' command to restart the router."}

Post-Check Verification

```
show interfaces detail | match ALARM_4135
show routing-table | match ALARM_4135
```

```
show log | match ALARM_4135
```