

Juniper PE Router Alarm Handling Procedure (ALARM_6420)

Node: Juniper-PE-Chennai-TN-95 | **Vendor:** Juniper | **Severity:** Minor | **Alarm Code:** ALARM_6420

Description

Alarm code ALARM_6420 on Juniper PE Router (Juniper-PE-Chennai-TN-95) indicates a Minor issue. This SOP outlines the troubleshooting steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Mismatched BGP AS Numbers	Medium
Incorrect Route Reflectors Configuration	High
BGP Session Down	Low

Diagnostic Commands

```
show bgp summary
show bgp summary | grep Juniper-PE-Chennai-TN-95
show bgp neighbors
```

Resolution Steps

- Step 1: {'Step': 1, 'Description': 'Verify BGP AS Numbers Mismatch', 'Commands': ['show bgp summary | grep AS-Number']}
- Step 2: {'Step': 2, 'Description': 'Check Route Reflectors Configuration', 'Commands': ['show bgp rr-group']}
- Step 3: {'Step': 3, 'Description': 'Verify BGP Session Status', 'Commands': ['show bgp neighbors']}
- Step 4: {'Step': 4, 'Description': 'Update Route Reflectors Configuration', 'Commands': ['set rr-group ', 'commit']}

Post-Check Verification

```
show bgp summary
show bgp neighbors
```