

Provider Edge Router (Juniper-PE-Delhi-NCR-28)

Alarm Response SOP

Node: Juniper-PE-Delhi-NCR-28 | **Vendor:** Juniper | **Severity:** Warning | **Alarm Code:** ALARM_9684

Description

This Standard Operating Procedure outlines the steps to be taken in response to a warning alarm (ALARM_9684) on the Juniper-PE-Delhi-NCR-28 provider edge router.

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive routing protocol updates	High
Configuration issue with the routing protocol	Medium
Hardware failure or degradation	Low

Diagnostic Commands

```
show system resources
show route summary
show route protocol
show configuration
```

Resolution Steps

Step 1: {'Step': '1. Check CPU utilization and routing protocol updates', 'Action': 'Run command: show system resources; show route protocol' }

Step 2: {'Step': '2. Check configuration for routing protocol', 'Action': 'Run command: show configuration | grep ' }

Step 3: {'Step': '3. Verify hardware status', 'Action': 'Run command: show chassis hardware'}

Step 4: {'Step': '4. Adjust routing protocol timers or filter out unnecessary updates', 'Action': 'Run command: set protocol timer ; commit'}

Step 5: {'Step': '5. Reboot the router if issue persists', 'Action': 'Run command: request system reboot'}

Post-Check Verification

```
show system resources
show route summary
show route protocol
```

```
show configuration
```