

Juniper PE Router SOP for Alarm ALARM_9263: Critical FPC Failure

Node: Juniper-PE-Kolkata-WB-117 | **Vendor:** Juniper | **Severity:** Critical | **Alarm Code:** ALARM_9263

Description

This SOP outlines the steps to diagnose and resolve a Critical FPC failure on the Juniper Provider Edge Router, Node ID: Juniper-PE-Kolkata-WB-117.

Potential Root Causes

Cause	Probability
FPC Hardware Failure	High
Software Misconfiguration	Medium
Power Supply Issues	Low

Diagnostic Commands

```
show chassis
show chassis hardware
show chassis fpc
show system uptime
show log messages
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the FPC', 'CLI_Command': 'request system power fpc 0'}
- Step 2: {'Step': 'Check for software misconfiguration', 'CLI_Command': 'show configuration'}
- Step 3: {'Step': 'Replace the FPC if hardware failure is confirmed', 'CLI_Command': 'request chassis fpc replace 0'}
- Step 4: {'Step': 'Verify power supply functionality', 'CLI_Command': 'show chassis power'}

Post-Check Verification

```
show chassis
show chassis hardware
show chassis fpc
show system uptime
```

show log messages