

Nokia Core Router ALARM_4106 SOP

Node: Nokia-Core-Bangalore-KA-1 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_4106

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the ALARM_4106, a Minor alarm on the Nokia Core Router at Bangalore-KA-1.

Potential Root Causes

Cause	Probability
Misconfigured Routing Protocol Parameters	High
Hardware Failure in the Routing Module	Medium
Software Bug in the Routing Protocol Stack	Low

Diagnostic Commands

```
show alarm detail ALARM_4106
show routing protocol parameters
show hardware module status
```

Resolution Steps

- Step 1: {'Step': '1. Check the routing protocol parameters', 'Action': "Verify the routing protocol parameters using the command 'show routing protocol parameters'. If the parameters are misconfigured, correct them and save the changes."}
- Step 2: {'Step': '2. Check the hardware module status', 'Action': "Use the command 'show hardware module status' to check the status of the routing module. If the module is faulty, replace it with a new one."}
- Step 3: {'Step': '3. Reset the routing protocol stack', 'Action': "Use the command 'reset routing protocol stack' to reset the routing protocol stack. This may resolve the issue if it is caused by a software bug."}

Post-Check Verification

```
show alarm detail ALARM_4106 (verify that the alarm is cleared)
show routing protocol parameters (verify that the parameters are correctly configured)
show hardware module status (verify that the routing module is functioning properly)
```