

Nokia Core Router Alarm Handling Procedure for ALARM_9112

Node: Nokia-Core-Bangalore-KA-1 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_9112

Description

This SOP outlines the steps to diagnose and resolve the ALARM_9112 issue on Nokia Core Router Bangalore KA-1.

Potential Root Causes

Cause	Probability
Faulty Transponder Module	High
Misconfigured BFD Session	Medium
Software Bug	Low

Diagnostic Commands

```
show transponder
show bfd neighbors
show version
show processes
```

Resolution Steps

Step 1: {'Step': '1. Check Transponder Module Status', 'Action': 'Run show transponder command to verify the status of the transponder module.'}

Step 2: {'Step': '2. Verify BFD Session Configuration', 'Action': 'Run show bfd neighbors command to verify the BFD session configuration. If misconfigured, correct the configuration and save it.'}

Step 3: {'Step': '3. Upgrade Software (if applicable)', 'Action': 'Run show version command to check for software updates. If available, upgrade the software and restart the router.'}

Step 4: {'Step': '4. Restart Router', 'Action': 'Run reload command to restart the router.'}

Post-Check Verification

```
show transponder
show bfd neighbors
show version
```