

Nokia Core Router Alarm Handling Procedure

Node: Nokia-Core-Bangalore-KA-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_1044

Description

This SOP outlines the steps to handle the ALARM_1044 on Nokia Core Router Bangalore KA-2. The alarm is reported with a severity of Minor.

Potential Root Causes

Cause	Probability
Interface Loopback Detection Failure	Medium
Misconfigured Loopback Detection Settings	High
Hardware Issues with Interface	Low

Diagnostic Commands

```
show interface info
show interface loopback-detection
show version
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check interface loopback detection settings', 'Action': "Run the command 'show interface loopback-detection' to verify settings", 'CLI_Command': 'no loopback-detection'}
- Step 2: {'Step': 'Verify interface loopback detection is enabled', 'Action': "Run the command 'show interface loopback-detection' to verify settings", 'CLI_Command': 'enable loopback-detection'}
- Step 3: {'Step': 'Check for hardware issues', 'Action': "Run the command 'show interface info' to verify interface status", 'CLI_Command': 'interface no shutdown'}

Post-Check Verification

```
show interface loopback-detection
show interface info
show tech-support
```