

Nokia Core Router SOP for Alarm Code ALARM_7584

Node: Nokia-Core-Chennai-TN-2 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_7584

Description

This Standard Operating Procedure outlines the steps to be taken to diagnose and resolve a major alarm on the Nokia Core Router, Chennai-TN-2. The alarm code ALARM_7584 indicates a critical issue affecting the core routing functionality.

Potential Root Causes

Cause	Probability
Hardware failure in the Nokia Core Router	High
Software bug or misconfiguration in the routing protocol	Medium
High network traffic or congestion	Low

Diagnostic Commands

```
show system alarm
show system resource
show ip bgp summary
show ip ospf neighbor
```

Resolution Steps

- Step 1: {'Step': '1. Identify the root cause of the alarm', 'Description': 'Run the show system alarm command to identify the source of the alarm.'}
- Step 2: {'Step': '2. Check hardware health', 'Description': 'Run the show system resource command to check for any hardware issues.', 'Command': 'show system resource'}
- Step 3: {'Step': '3. Verify routing protocol configuration', 'Description': 'Run the show ip bgp summary command to verify BGP configuration.', 'Command': 'show ip bgp summary'}
- Step 4: {'Step': '4. Clear and re-establish routing protocols', 'Description': 'Clear the routing protocol neighbors and re-establish them.', 'Command': 'clear ip bgp *'}
- Step 5: {'Step': '5. Verify the fix', 'Description': 'Run the show ip bgp summary command to verify that the routing protocol is stable.'}

Post-Check Verification

```
show ip bgp summary
show ip ospf neighbor
```

```
show system alarm
```