

Nokia Core Router - Minor Alarm ALARM_7790 SOP

Node: Nokia-Core-Chennai-TN-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_7790

Description

The ALARM_7790 minor alarm indicates a potential issue with the Nokia Core Router's routing protocol. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured routing protocol parameters	High
Issue with routing protocol neighbor connections	Medium
Temporary software bug	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors
show ip bgp rib
debug bgp
```

Resolution Steps

- Step 1: {'Step': 'Verify routing protocol configuration', 'Action': 'Check the routing protocol configuration and ensure that all parameters are correctly set', 'CLI_Commands': 'show running-config | include bgp'}
- Step 2: {'Step': 'Check neighbor connections', 'Action': 'Verify that all routing protocol neighbor connections are stable', 'CLI_Commands': 'show ip bgp neighbors'}
- Step 3: {'Step': 'Reset routing protocol', 'Action': 'Reset the routing protocol to restart all processes', 'CLI_Commands': 'clear bgp'}

Post-Check Verification

```
show ip bgp summary
show ip bgp neighbors
show ip bgp rib
```