

Nokia Core Router SOP for ALARM_7824 in Chennai-TN-2 Node

Node: Nokia-Core-Chennai-TN-2 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_7824

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7824, a critical alarm indicating a severe issue on the Nokia Core Router in Chennai-TN-2 Node.

Potential Root Causes

Cause	Probability
Router Resource Exhaustion	High
Software Bug or Misconfiguration	Medium
Hardware Failure	Low

Diagnostic Commands

```
show system resource
show system software version
show system configuration
show system alarm history
```

Resolution Steps

- Step 1: {'Step': 'Check Router Resource Utilization', 'Action': "Run the command 'show system resource' to check for resource exhaustion. If resource utilization is high, adjust the router configuration to free up resources."}
- Step 2: {'Step': 'Verify Software Version', 'Action': "Run the command 'show system software version' to check for software updates. If a software update is available, apply it to resolve the issue."}
- Step 3: {'Step': 'Review Configuration', 'Action': "Run the command 'show system configuration' to review the router configuration. If a configuration issue is found, correct it to resolve the alarm."}
- Step 4: {'Step': 'Check Alarm History', 'Action': "Run the command 'show system alarm history' to review the alarm history. If the alarm has been recurring, investigate the root cause and take corrective action."}
- Step 5: {'Step': 'Replace Faulty Hardware', 'Action': "If the alarm is caused by a hardware failure, replace the faulty hardware to resolve the issue."}

Post-Check Verification

```
show system resource
show system software version
show system configuration
show system alarm history
```