

# SOP for Resolving Alarm ALARM\_6204 on Nokia Core Router Delhi-NCR-2

**Node:** Nokia-Core-Delhi-NCR-2 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM\_6204

## Description

This SOP outlines the procedures to diagnose, resolve and verify the fix for the ALARM\_6204 on the Nokia Core Router Delhi-NCR-2.

## Potential Root Causes

| Cause                                    | Probability |
|------------------------------------------|-------------|
| Hardware failure in the routing engine   | High        |
| Software bug in the routing protocol     | Medium      |
| Misconfiguration of the routing protocol | Low         |

## Diagnostic Commands

```
show tech-support
show routing-engine
show routing-protocol
debug routing-protocol
```

## Resolution Steps

- Step 1: {'Step': 'Power cycle the routing engine', 'Description': 'Reboot the routing engine to clear any temporary issues', 'CLI\_Command': 'request system reboot'}
- Step 2: {'Step': 'Verify routing protocol configuration', 'Description': 'Check the routing protocol configuration for any misconfigurations', 'CLI\_Command': 'show routing-protocol'}
- Step 3: {'Step': 'Update software to latest version', 'Description': 'Update the software to the latest version to fix any known bugs', 'CLI\_Command': 'request system software update'}
- Step 4: {'Step': 'Replace hardware if necessary', 'Description': 'Replace the hardware if the issue is due to a hardware failure', 'CLI\_Command': ''}

## Post-Check Verification

```
show routing-engine
show routing-protocol
show tech-support
```