

Nokia Core Router SOP for Alarm ALARM_2495: Minor Issue

Node: Nokia-Core-Kolkata-WB-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_2495

Description

This Standard Operating Procedure (SOP) outlines the steps to identify and resolve the ALARM_2495 error on the Nokia Core Router Node ID: Nokia-Core-Kolkata-WB-2.

Potential Root Causes

Cause	Probability
Route Policy Configuration Error	High
IP Prefix List Misconfiguration	Medium
BGP Session Down due to Peer Authentication Issues	Low

Diagnostic Commands

```
show route-policy
show ip prefix-list
show bgp neighbors
```

Resolution Steps

- Step 1: {'Step': '1. Verify Route Policy Configuration', 'Action': 'Use CLI command: show route-policy to check for any configuration errors.', 'Expected Outcome': 'Corrected configuration or error message indicating configuration issue.'}
- Step 2: {'Step': '2. Check IP Prefix List Configuration', 'Action': 'Use CLI command: show ip prefix-list to verify prefix list configuration.', 'Expected Outcome': 'Corrected configuration or error message indicating configuration issue.'}
- Step 3: {'Step': '3. Verify BGP Session Status', 'Action': 'Use CLI command: show bgp neighbors to verify BGP session status.', 'Expected Outcome': 'BGP session up and running or error message indicating session issue.'}
- Step 4: {'Step': '4. Correct Configuration Errors', 'Action': 'Use CLI command: apply route-policy [route-policy-name] to correct configuration errors.', 'Expected Outcome': 'Alarm resolution and correct configuration.'}
- Step 5: {'Step': '5. Verify Alarm Resolution', 'Action': 'Use CLI command: show alarm to verify alarm resolution.', 'Expected Outcome': 'Alarm status: Cleared.'}

Post-Check Verification

```
show alarm
show route-policy
show ip prefix-list
show bgp neighbors
```