

Nokia Core Router SOP for Alarm ALARM_5834

Node: Nokia-Core-Kolkata-WB-2 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_5834

Description

Alarm ALARM_5834 is triggered on Nokia Core Router Node ID: Nokia-Core-Kolkata-WB-2, indicating a Major issue. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
High CPU utilization on the Route Reflector	High
Misconfigured Route Reflector Group	Medium
Software bug in the Route Reflector	Low

Diagnostic Commands

```
show cpu utilization
show route reflector group configuration
show route reflector group statistics
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization on the Route Reflector', 'Action': "run the command 'show cpu utilization' to identify high CPU processes", 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Verify Route Reflector Group configuration', 'Action': 'check the configuration of the Route Reflector Group for any misconfigurations', 'CLI_Command': 'show route reflector group configuration'}
- Step 3: {'Step': '3. Update software on the Route Reflector', 'Action': 'update the software on the Route Reflector to the latest version', 'CLI_Command': 'software update'}

Post-Check Verification

```
show cpu utilization
show route reflector group configuration
show route reflector group statistics
```