

Nokia Core Router SOP: Resolving ALARM_9560 on Nokia-Core-Mumbai-MH-2

Node: Nokia-Core-Mumbai-MH-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_9560

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_9560, a minor alarm on the Nokia-Core-Mumbai-MH-2 core router.

Potential Root Causes

Cause	Probability
Misconfigured routing protocol	Medium
Hardware failure in the routing engine	Low
Software issue with the OS or applications	Medium

Diagnostic Commands

```
show alarm all
show route summary
show hardware routing-engine
show system software
show system processes
```

Resolution Steps

- Step 1: {'Step': 'Verify routing protocol configuration', 'Action': "Check routing protocol configuration and make necessary changes using 'configure' mode", 'CLI_Command': 'show running-config | include '}
- Step 2: {'Step': 'Swap out faulty HW component', 'Action': 'Replace the faulty component with a new one and reboot the system', 'CLI_Command': 'switchover'}
- Step 3: {'Step': 'Update system software', 'Action': "Update the system software to the latest version using 'software update' feature", 'CLI_Command': 'software update now'}
- Step 4: {'Step': 'Restart system processes', 'Action': "Restart the system processes using 'process restart' command", 'CLI_Command': 'process restart'}

Post-Check Verification

```
show alarm all
show route summary
```

```
show system software  
show system processes
```