

Nokia Provider Edge Router (PE) Alarm Handling

SOP - ALARM_2664

Node: Nokia-PE-Chennai-TN-100 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_2664

Description

This SOP outlines the steps to investigate and resolve a Major alarm on Nokia Provider Edge Router (PE) node ID: Nokia-PE-Chennai-TN-100, triggered by alarm code ALARM_2664.

Potential Root Causes

Cause	Probability
Software fault in the routing protocol process	High
Hardware failure in the line card or route processor	Medium
Misconfiguration of the routing protocol	Low

Diagnostic Commands

```
show alarm
show cpu utilization
show memory utilization
show routing protocol process status
show interface detail
```

Resolution Steps

Step 1: {'Step': '1. Identify the affected routing protocol process', 'Action': "Use the command 'show routing protocol process status' to identify the process and its status."}

Step 2: {'Step': '2. Check for software faults', 'Action': "Use the command 'show alarm' to check if there are any software-related alarms."}

Step 3: {'Step': '3. Verify hardware integrity', 'Action': "Use the command 'show interface detail' to verify the interface status and 'show cpu utilization' and 'show memory utilization' to check for any hardware-related issues."}

Step 4: {'Step': '4. Check for misconfiguration', 'Action': "Verify the routing protocol configuration using the command 'show running-config routing-protocol'."}

Step 5: {'Step': '5. Restart the routing protocol process', 'Action': "Use the command 'clear routing protocol process' to restart the process."}

Post-Check Verification

```
show alarm
show routing protocol process status
show interface detail
show cpu utilization
show memory utilization
```