

Nokia PE Router ALARM_3315 Minor Alarm SOP

Node: Nokia-PE-Chennai-TN-100 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_3315

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the ALARM_3315 minor alarm on the Nokia PE Router. The alarm indicates a minor issue with the control plane, which may affect routing and forwarding.

Potential Root Causes

Cause	Probability
Incorrect configuration of control plane protocols	High
Software bug or defect in the control plane	Medium
Hardware failure or malfunction in the control plane	Low

Diagnostic Commands

```
show controller cpu
show cpu utilization
show ip int brief | include FastEthernet0/0/0/0
```

Resolution Steps

- Step 1: {'Step': '1. Check the control plane configuration', 'Action': "Verify the control plane protocols are correctly configured using the command 'show run | include control-plane'."}
- Step 2: {'Step': '2. Clear the control plane', 'Action': "Use the command 'clear control-plane' to clear any software-related issues. Verify the alarm clears and the control plane recovers."}
- Step 3: {'Step': '3. Check for hardware issues', 'Action': "Use the command 'show controller cpu' to check for any hardware-related issues. If issues are found, contact the hardware team for assistance."}

Post-Check Verification

```
show alarm history
show ip int brief | include FastEthernet0/0/0/0
```