

3rdParty MCAL Integration

Release Notes

Renesas RH850/P1x Version 1.1.80

Authors	Roland Süß
Status	Released



Document Information

History

Author	Date	Version	Remarks
Roland Suess	2015-10-05	1.0.0	Integration of Renesas package AUTOSAR_RH850_P1x_MCAL_E4.03
Andrej Gazvoda	2015-10-21	1.0.1	Integration of Renesas package AUTOSAR_RH850_P1x_MCAL_Ver4.00.04
Andrej Gazvoda	2015-10-21	1.0.2	Mantis_0026358_HotFix_20150226
Andrej Gazvoda	2016-07-21	1.1.0	Integration of Renesas package AUTOSAR_RH850_P1x_MCAL_Ver4.01.00
Andrej Gazvoda	2016-08-19	1.1.80	Integration of Renesas package AUTOSAR_RH850_P1x_MCAL_Ver4.01.01_Pre_ Release_CW32 Special Release for Nexteer

Reference Documents

No.	Source	Title	Version
[1]	Vector	TechnicalReference_3rdParty-MCAL-Integration.pdf	1.02.00

Scope of the Document

This document contains information about the integration of $3^{\rm rd}$ Party MCAL into Vector software stack.



Contents

1	MCA	L Integrat	ion	4
	1.1	Type of	f Integration	4
	1.2	MCAL I	Location within SIP	4
	1.3	Suppor	ted µController	4
	1.4	Used M	ICAL Packages	5
	1.5	Configu	uration Tools	5
	1.6	Suppor	ted Compilers	5
2	Vecto	or Comme	ent	6
	2.1	Known	Issues	6
		2.1.1	McuDemEventParameterRefs	6
		2.1.2	SpiDemEventParameterRefs	6
		2.1.3	McuClockReferencePoint	6
3	Glos	sary and A	Abbreviations	7
	3.1	Glossa	ry	7
	3.2	Abbrev	iations	7
4	Cont	act		8



1 MCAL Integration

1.1 Type of Integration

Comfort Integration

Vector tool DaVinci Configurator 5 is used for configuration

- > as comfort editor for Mcu component
- > as generic editor for other MCAL modules

Recommended workflow:

Generation and changes in configuration are done in DaVinci Configurator.

1.2 MCAL Location within SIP

The 3rd Party MCAL can be found in .\ThirdParty\Mcal_Rh850P1x\Supply. Please refer to chapter 'First Steps' in document TechnicalReference_3rdParty-MCAL-Integration.pdf [1].

1.3 Supported µController

This integration supports the Renesas RH850P1M target with the following devices:

R7F701304

R7F701305

R7F701310

R7F701311

R7F701312

R7F701313

R7F701314

R7F701315

R7F701318

R7F701319

R7F701320

R7F701321 R7F701322

R7F701323

R7F701364

R7F701365

R7F701362

R7F701363

R7F701366

R7F701367.



1.4 Used MCAL Packages

> AUTOSAR_RH850_P1x_MCAL_Ver4.01.01_Pre_Release_CW32

1.5 Configuration Tools

DaVinci Configurator 5

1.6 Supported Compilers

GreenHills (MULTI 6.1.4) and Compiler 2013.5.5



2 Vector Comment

Please consider the attached <code>TechnicalReference_3rdParty-MCAL-Integration.pdf</code> [1] for further information regarding Vector integration and setup of a project.

2.1 Known Issues

2.1.1 McuDemEventParameterRefs

For the case that parameters MCU_E_WRITE_TIMEOUT_FAILURE and MCU_E_CLOCK_FAILURE are configured with the same DemEventParameter, the following error message appears:

```
ERR101042: The value for the parameters 'MCU_E_WRITE_TIMEOUT_FAILURE' and 
< MCU_E_CLOCK_FAILURE'> present in the container 
'McuDemEventParameterRefs' should be unique. 
Path: /ActiveEcuC/Mcu/McuModuleConfiguration/McuDemEventParameterRefs
```

In fact, the values *should not be* unique.

2.1.2 SpiDemEventParameterRefs

For the case that parameters SPI_E_HARDWARE_ERROR and SPI_E_DATA_TX_TIMEOUT_FAILURE are configured with the same DemEventParameter, the following error message appears:

```
ERR083093: The reference path

</ActiveEcuC/Dem/DemConfigSet/DemEventParameter>
configured for the parameters 'SPI_E_HARDWARE_ERROR' and
'SPI_E_DATA_TX_TIMEOUT_FAILURE' in the container
'SpiDemEventParameterRefs'should be unique.
Path: /ActiveEcuC/Spi/SpiDriver/SpiDemEventParameterRefs
```

In fact, the values *should not be* unique.

2.1.3 McuClockReferencePoint

Multiplicity of container McuClockReferencePoint in the Mcu description files R403_MCU_P1M_04_05.arxml R403_MCU_P1M_10_to_15_18_to_23.arxml was wrong.



Caution

You have to patch the description files in your Mcal package before you start the 3rdPartyMcalIntegrationHelperTool. The necessary patches are already done here:



3 Glossary and Abbreviations

3.1 Glossary

Term	Description
3 rd party components / MCAL	BSW modules not provided by Vector. Vector may have integrated the software within the SIP but does not take over any responsibility regarding functionality of these modules.
DaVinci Configurator	Configuration and generation tool for Vector MICROSAR components

Table 3-1 Glossary

3.2 Abbreviations

Abbreviation	Description
MCAL	Microcontroller Abstraction Layer
AUTOSAR	Automotive Open System Architecture
SIP	Software Integration Package (as provided by Vector)

Table 3-2 Abbreviations

7



4 Contact

Visit our website for more information on

- > News
- > Products
- > Demo software
- > Support
- Training data
- > Addresses

www.vector.com