

Air-X-Changers

# **ES-PRO-003-0: Engineering Change Notice**

(Engineering Standards and Specifications)

	This doci	ument has an effectivit	:y of/	/	
Approve	d By:	Director of Engineering	Date	e:	
Approve	· · · · · · · · · · · · · · · · · · ·	Production Engineering Manager	Date	2:	
Approved By:		Drafting Supervisor	Date	e:	
	5 .				

Revision	Date	Description	Author	Approved by
0	01/16/18	New	HV	

Electronic documents, once printed, are uncontrolled and may become outdated.

Refer to the company Intranet for the current revision.

**Proprietary Information:** This document contains proprietary information belonging to Harsco Industrial Air-X-Changers and must not be wholly or partially reproduced nor disclosed without written permission.

#### 1. Purpose

1.1. Establish a procedure for Project Engineers on coolers with electric equipment wiring requirements.

#### 2. Scope

2.1. Define PE responsibilities and processes when electric equipment wiring is called out on the DBP.

### 3. Definitions, Terms & Abbreviations

- 3.1 JB Junction Box
- 3.2 BOM Bill of Material
- 3.3 JBI Job Instructions
- 3.4 PTL Parts List
- 3.5 DBP Data Book Pricing
- 3.6 LBR- Labor Routing
- 3.7 VB Vibration Switch
- 3.8 VT Vibration Trasmitter
- 3.9 CRT Certified Drawing
- 3.10 HDR Header
- 3.11 STR Structure
- 3.12 PBK PriceBook
- 3.13 SL SyteLine
- 3.14 PE Project Engineer
- 3.15 FF Flatter Files

#### 4. References & Supporting Documents

- 4.1. SyteLine
- 4.2. PriceBook
- 4.3. Quote Letter

## 5. Responsibilities

- 5.1 The PE shall be responsible for the following:
  - 5.1.1. Identify when electric equipment wiring is required
  - 5.1.2. Adding electric equipment wiring requirements to the LBR
  - 5.1.3. Ensure all specs are identified for electric equipment wiring
  - 5.1.4. Identify location of JB on CRT drawing if applicable
  - 5.1.5. Adding JB to PTL if applicable.

- 5.1.6. Requesting wiring diagram from Purchasing of electric equipment that needs to be wired.
- 5.1.7. Issuing wiring diagram to FF.
- 5.1.8. Verify that JB location has been identified on STR prints if applicable.

#### 6. Procedure


- 6.1 PE steps production impact and priority level:
  - 6.1.1. Review entered cooler order
    - 6.1.1.1. If electric equipment wiring is called out in the DBP, add it to the LBR
    - 6.1.1.2. If description is not detailed, request for more information from the sales rep.
  - 6.1.2. Check box in LBR for "Junction Box and or/Wiring."
  - 6.1.3. Contact sales if not all information on electric equipment wiring is provided.
  - 6.1.4. Confirm JB is located on CRT drawing if applicable.
  - 6.1.5. Add JB part number to PTL if applicable.
  - 6.1.6. Email purchasing once PTL is issued to receive wiring diagrams of electric equipment that needs to be wired.
  - 6.1.7. Issue wiring diagrams to FlatterFiles in Eng Paper folder.

#### 7. Examples


#### PTL - 177083


VB2051	1	FAN SHEAVE, 50 Inch OD
VB2730	1	FAN SHEAVE BUSHING, J TYPE, 2-7/16 Inch BORE
VB2050	1	MOTOR SHEAVE, 6.7 Inch OD
VB2495	1	MOTOR SHEAVE BUSHING, <b>SK</b> TYPE, <b>2-1/8</b> Inch BORE
CT1169	1	TRNS,VIBRA,METRX,ST5484E-121-020-00*
HW0130	1	HDWE,JUNCTBOX,10X8X4,HOFFMAN- A-1008CHNF
STRUCTURE I	FINISH	
	GAL	VANIZED STRUCTURE AND FRAME W/PAINTED HEADERS
THE ADED EIGH	CTT.	

<u>CRT</u>



Page 5 Revision 0 Effective 00/00/0000





**Proprietary Information:** This document contains proprietary information belonging to Harsco Industrial Air-X-Changers and must not be wholly or partially reproduced nor disclosed without written permission.